"BEST PRACTISE" BAGI KERJA-KERJA PENYELIAAN PEMBINAAN JAMBATAN DO & DONT'S IN BRIDGE CONSTRUCTION







Ministry: NKVE link developer ignored safety rules

BY SHOW THON.

PETALING WYA: The developer of the regulations by allowing motories to interestenal conference, Merce-Datti Rhoud Rahman Rakat

"We an offence to allow traffic on syntentials made where there is construction, as

many places around the Klang Valley. when carrying out the project.

good the interpretations we have purioud Safety and Health (DOSK) NAVE Stan Mery Link neglected salety to fair. The paid often covering an director general Also Balan Clie Man. travel on the road below the income. Future intelligible forces and Clarkes. Seria on how the company intended to - into the cause of the Provincial proplets figures that collapsed on Sanday ges In The Brodislass World, organised discountle the remaining structure of sad Deputy Human Resource Minutes . By University Televologi Marcin Fa- the collapsed Spower, reports SDMON . soon with the authorities personally cults of Management and Technology 100000

this will exprove exercising and the published, and the main contractor it intenduces or the More Link are will. "Take are working closely with the appointed, Chang Hyap Your 5ds Blot, howeving prin accords: "Deformately, this is buppening at ... had failed to halfd safety conditions

entitied off and design should be good when right potens of the figures entities it would not enduryer passing. develor of 3P Seta.

Athensis the debris on the real He senseled that the developer, SP had been cleaned, parts of the elevated toos by today.

strend is expected to be opened by import and will haud it over to the Rehtfully, those sections should be - Note Kingladesh labourers were in- Disputa, all invasors must be taken to - authorities," said Khur Chap Sen, a

"Subry should be our pricers; in . In Seventian, Department of Occo- year on solery and health manager

Works Department in investigation

Meanwhile, after further discus-57 Sets and it would submit a followup report with more detailed advenu-

esternal specialist contraction and "Secr the Boke Kips (but Alam consultants to prepare the follow-up



Don't have JKR bridges collapse during construction



Arrangement of reinforcement for tranverse beam not following construction drawing.




Insufficient reinforcement anchorage length provided at arch beam.



Spacing of reinforcement does not follow specification



Joint in adjacent sheaths shall be staggered by at least 300mm



Installation of steel reinforcement at pier crosshead does not follow construction drawing





Do have common sense
Don't let prestressing tendon exposed to weather to avoid
corrosion.



All prestressing tendons shall be stored clear of the ground and protected from weather in accordance to the specification.



Tendon was corroded and not protected as per specification



Distance between edge of beam to ballast wall exceeded the designated distance (50mm)




10mm minimum diameter vent shall be provided at all high and low point on cable profile in accordance to the specification for the purpose of monitoring during grouting works. The maximum permitted grout pressure at the point of injection inlet shall be 1.0 N/sq.mm.



Embankment fill has been removed

Abutment 'B' was shifted 150mm towards river due slope failure of approach embankment.



Abutment has been shifted approximately 150mm.



Sagging of walk way slab



Tranverse beam not constructed below walk way slab (Not following construction drawing)



Pocket for end stress bar not immediately grouted.




Pocket for end stress bar not immediately filled with shrinkage compensating concrete.



Walkway not constructed in line between main span with approach road.



Kink at parapet could be hazards to drivers due direct impact of vehicles.




Insufficient concrete cover



Cracking at beam exposing the reinforcement




Damaged shear keys






Don't certify a project completed Starter bars there, but intermediate diaphragm not constructed.





Accidental impact of construction machinery



Water pipe was laid by punching through the wall of roads side drain.



Deviation of anchor bolts deviated from the centreline of pile cap.

Don't have poorly constructed works





No leveling mortar before installation of precast parapets



Broken and fractured anchoring bolt of precast parapet



Corroded M24 h.d. used to tie the precast parapet shows that h.d. bolt was installed without approved resin or grouts



Anchor bolts shall be casted together with parapet wall to receive handrail.



Buckling at steel baseplate occured.




- Existing painting/coating was not removed before welding being carried out.
- The purpose is to avoid the mixing of chemical between painting and weld materials (contamination).
- Disburb/Affect the welding strength



Don't backfill earthwork from one side only


DO'S



Do have a proper design for all D&B project



Good quality of bridge works.



Do have concrete for bored piles poured at least 1000mm above cut-off level to remove the low quality concrete such as laitance and mud before concreting for pile cap.



Do use steel formworks to produce high quality of concrete finishing.




Piers: Good concrete finishing



Scaffolding was designed for the safety and to produce high quality of superstructure work.




Temporary bridge was designed according to Code of Practice for the safety of temporary works at site.









Strength Requirements

Grade 40

Bases, pile caps, abutments, retaining walls and parapets

Durability Requirement

Concrete Mix		
20mm graded granite (kg/m³)	1086	
River sand (kg/m³)	715	
Water (kg/m³)	150	
OPC Type (kg/m ³)	-	
Mas 30 (kg/m ³)	410	
Silica Fume (%)	5	
Slump (mm)	150	
Retarder (ml/m ³)	1500	
Daracem (ml/m³)	10000	
Agg/Binder Ratio	4.19	
Water/Binder Ratio	0.34	

Control Heat Of Hydration

The actual pile cap size was 17m x 14m x 2.50m. It was recorded that the maximum concrete temperature of the mix exceeded 90°C and the temperature differentials were in order of 35 to 40°C.

In order to control the heat of hydration, a mix which contained less cement and silica fume was introduced together with using internal cooling system to properly control the generated heat and temperature differentials.

Durability Requirement

	Initial Surface Absorption Test (ISAT) (ml/m2/s)	Rapid Chloride Permeability (RCPT) (coulombs)
Insitu Concrete (Grade 40, 60 & 80)	0.1	1000
Precast Concrete (Grade 60)	0.5	500



ISAT TESTING IN PROGRESS



RCPT TESTING IN PROGRESS



Curing of segment with automatic sprinkling system



Curing of segment with mist (fogging)

QUALITY CONTROL DURING CONSTRUCTION

The segments were water cured for fourteen (14) days, followed by the application of a curing compound for a further seven (7) days. In this period of curing, the segments were protected from direct wind and sun in the curing chamber.



STACKING OF RAMP SEGMENT

The stripping of mould for each segment could only be done once the segment reaches a compressive strength of 12 MPa.



LIFTING OF COMPLETED SEGMENT


Whereas the segments could only be lifted until the concrete strength reached a minimum strength of 25 Mpa. The lifting was carried out by a straddle carrier capable of lifting the heaviest segment of 125 tonne.



The completed bridge



View of Twin Leaf Pier Ribbed Finishes



General View of The Ramp

Final Connection of Main Segments And Site Frames







Do understand our CONTRACT

- Obligation of the Government
- Obligation of the Contractors

Do look at DRAWINGS

- Construction drawings
- Details
- Notes

Do look at BQ, MOM & SPECIFICATIONS

- Method of Construction
- Quality of finish product

Thank you