




Technical Issues Faced on Completed Government Hospital Project

Forensic Findings

Mesyuarat Tahunan Jurutera Mekanikal 2016
Cawangan Kejuruteraan Mekanikal, Ibu Pejabat JKR
5 September 2016

Introduction

- ▶ Forensic Division had conducted 75 nos of inspections for various types of government buildings since 2011 until august 2016
 - ▶ **17 no's of inspections** were carried out in the **hospital building**
 - ▶ Statistic is not included with others health facilities such as Clinics and District Health Office
- 

Problem Statements



Mold



High Space
Humidity




Condensation



Noise Issues


Statistic 2011–2016 (17 Case)




1.0 *Condensation*

Condensation

Locations Condensation Happens





Reason

- ▶ This condition occurs due to reasons as below:
 - Surface Temp Lower Than Dew Point Temp



Dew Point Temp : 18°C

Surface Temp : 17.5°C

Duct Insulation Retrofitting

Before



Duct condensation on ducting.
Duct thickness 10 mm

After Retrofitting



Ducting Insulation 20mm (PE
Foam Laminated With
Aluminums Foil).

Perimeter Opening (Cross Ventilation)



Louvers Opening

Louvers Opening

2.0 HIGH RH

Reason

- ▶ This condition occurs due to reasons as below:
 - **Building Load** – Building Load Less Than Design Load
 - **Coil Capacity** – Oversized
 - **System Failure** – The Possibility of System Failure

2.1 Cooling Coil Retrofitting

Retrofitting- *Cooling coil area reduction*

Before Retrofit

Average temp: 22°C
Average RH: 68%


RH



Dry Bulb temp

Load density: 53 btu/hr.sq.ft

Retrofitting- *Cooling coil area reduction*



3.0 Low Supply Air Flow Rate / Air Change Rate

Reason

- ▶ This factor occurs due to reasons below:
 - Insufficient **effective duct length** immediately after AHU
 - Poor **fan discharge** ducting arrangement
 - AHU fan **wrong direction installation**
 - Wrong **guide vane** installation
 - **Duct leakages**
 - **Insufficient return grille**

Retrofitting- *System Effect*

DUCT REROUTING Before




AHU duct outlet for General Medicine zone is at 90 deg relative to flow discharge direction from fan.

Design AirFlow $> 6250 \text{ l/s} \sim 13000 \text{ cfm}$

Measured AirFlow $> 3108 \text{ l/s} \sim 6500 \text{ cfm}$




Propose Ducting Wall Penetration



Retrofitting– *System Effect*

DUCT REROUTING After



Design AirFlow $> 6250 \text{ l/s} \sim 13000 \text{ cfm}$

Measured AirFlow $> 3108 \text{ l/s} \sim 6500 \text{ cfm}$ (Before Retrofit)

Measured AirFlow $> 4351 \text{ l/s} \sim 9100 \text{ cfm}$ (After Retrofit)


40% Air Flow Improvement

Retrofitting – *System Effect*

FAN REORIENTATION Before

Recommended practice

As installed



Design AirFlow $> 5550 \text{ l/s} \sim 12000 \text{ cfm}$

Measured AirFlow $> 2500 \text{ l/s} \sim 5300 \text{ cfm}$ (Before Retrofit)

Retrofitting – *System Effect*

FAN REORIENTATION After




Design AirFlow $> 5550 \text{ l/s} \sim 12000 \text{ cfm}$

Measured AirFlow $> 2500 \text{ l/s} \sim 5300 \text{ cfm}$ (Before Retrofit)


Measured AirFlow $> 3000 \text{ l/s} \sim 6400 \text{ cfm}$ (After Retrofit)

Improved 20 % Air Flow

Low Air Flow Rate



Air flow Improvements




Ref case:
Retrofitting works
After duct reseal, supply air flow rate increases from 1900 cfm to 2500 cfm. An improvement of 32%.



Existing duct seal was applied at duct corner only. New duct seal was applied along all transverse joint perimeter.

Low Air Flow Rate



Duct elbow

Guide vane installation (wrong) resulting in less air flow and noise

Low Air Flow Rate


**Low supply air flowrate
/ Air Change Rate)**

Insufficient effective duct length
(system effect)

Insufficient return air grilles

Insufficient number of return grilles. Added static loss and reduction of flow

1 return grille vs 6 supply diffusers



4.0 Excessive FCU/AHU CFM

Reason

- ▶ FCU Capacity not meet/ the design parameter

Wrong Capacity Selection




Suggestions

- ▶ VSD installation
- ▶ New FCU with suitable room capacity

5.0 Operations & Maintenance

Reason


- ▶ Poor maintenance supervisory



DIRTY AIR FILTER



COOLING COIL CHOKE




Impact of Poor Maintenance

VIBRATION IN CEILING
SPACE 4 (WITH
ADDITIONAL TIE-ROD)

Air Filter clog



Fan Selection



Conclusion

- ▶ High relative humidity and duct condensation are among the highest number of reported forensic cases in healthcare facility.

So..We must focus to

- ▶ Comprehensive design review
- ▶ Equipment Selection Review
- ▶ Close Supervision of Installation
- ▶ Proper Testing & Commissioning
- ▶ Operations & Maintenance