

FORENSIC SITE INVESTIGATION & INSTRUMENTATION



Ir. Dr. M. Farid Ahmad
DFY Consult & CSL Soil Centralab

CAUSE, EFFECT OF FAILURE AND RESULTS OF INVESTIGATION




WHAT IS A FAILURE?


Behaviour not in agreement with the expected conditions of stability, or as lacking freedom from necessary repair, or non-compliance with the desired use and occupancy of the completed structure.

Mohr Circles & Failure Envelope

The soil element does not fail if the Mohr circle is contained within the envelope





Initially, Mohr circle is a point





Mohr Circles & Failure Envelope

The soil element does not fail if the Mohr circle is contained within the envelope




Mohr Circles & Failure Envelope


As loading progresses, Mohr circle becomes larger...



.. and finally failure occurs when Mohr circle touches the envelope

Orientation of Failure Plane





***FACTORS
THAT CONTRIBUTE TO
GEOTECHNICAL FAILURES***

IGNORANCE

CARELESSNESS

ATTITUDE

***HUMAN
ERRORS***

***FALSE
ECONOMY***

GREED

IGNORANCE

Frequent human ignorance

- Incompetent staff or personnel incharge of site investigation, design, preparation of working drawing and specification of works.
- Absence of proper site investigation.
- Failure to understand or making wrong interpretation of geotechnical investigation results.
- Assumption of vital responsibility by man without the necessarily professional know-how.

IGNORANCE

Frequent human ignorance

- Lack of proper coordination between the various parties.
- Job performed by incompetent contractor.
- Job supervised by personnel lacking intelligence, training or experience.
- Faulty design practice or failure to comply with codes requirement or poor drafting.
- Changing someone else's design without the knowledge of the original designer nor understanding the original designer's assumptions.



CARELESSNESS

- Design oversight which includes a number of errors that occur frequently.
- Carelessness on the part of the contractor and site supervisors.

FALSE ECONOMY

- Economic consideration is certainly a requirement, apart from engineering and safety considerations, in making an engineering decision.
- However, one should not bias a decision based on false economy.



GREED

- It is certainly not wrong to covet richness, but one should not be greedy and try to accumulate wealth through illicit means.
- All practice by contractor can be checked through proper and honest supervisions.

ATTITUDE

- Attitude plays an important role in determining the performance of a person and the quality of his work.
- His work will invariably be careless and error prone, which can trigger many problems.
- If construction failures are to be averted, it is necessary among others, for the engineers and the contractors to have the right work attitude.
- The government “Look East Policy” is part of a strategy to instill a sense of discipline and dedication among the citizen of this country, particularly the government servants, to help cultivate the right attitude towards work.

**SITE
INVESTIGATION**

DESIGN

USAGE

**TECHNICAL
SHORTFALLS**

DRAWING

CONSTRUCTION

SPECIFICATION

CAUSE AND EFFECT

- Activities and their effect on foundation, settlement, slope stability and vibration

REPORT

- Installation record
- Data sheet
- Direct plots

Garbage In Garbage Out

PREINSTALLATION ASSEMBLY AND CHECKING


tube no	reduced level (m)		tube length (m)	magnet reference no	magnet design level (m)	position of magnet from bottom of tube (m)
	from	to				
1			3 m			
2			3			
3			3			
4			3			
5			3			
6			0.5m			
assembled and check by			HAKIM		date 28/01/2002	

INSTALLATION

borehole backfill			chainage	198.28	offset (m)	
water	cement	bentonite	orientation of inclo keyways			OK
	1	4	other information			
volume (m ³)						

COMMISSIONING

[illegible]

inclinomometer base data file name	Wc - 01	date	29.04.2012
witnessed/approved by Engineer	 MANAGEMENT SDN BHD Anggerik Vanilla M 31 seksyen 31		

INSTALLATION DIAPHRAGM

start date	23/01/2002	ground level (m)	16.54 m
depth (m)		casing dia. (mm)	100
	0	ground level	
finish date	23/01/2002	driller name	
final depth	15.0	total casing length (m)	15.0
total casing length (m)	15.20	total casing depth (m)	15.0

INCLINOMETER
EXTENSOMETER

contract no	
----------------	--

inclinomater/ extensometer ref. no	INC - 0.1 24 - 8
--	---------------------

date/time installed	5:00 pm 03/01/2003
installed by	Hakim / A/ce



soil centralab
sendirian berhad

SITE WORKSHEET

SP1

PREINSTALLATION ASSEMBLY AND TESTING

piezometer type	Casagrande	test date	15/01/2002	1st standpipe length (m)	
serial no	-	test by	Hani3	10.50	
remarks	Reference Level from TANJ ASSUMED LEVEL + 10.00.				

SITE INFORMATION

ground surface conditions	SLOPE
remarks	-


INSTRUMENT LOCATION

chainage	198.940
offset	2nd BERM N/B.

INSTALLATION IN SAND POCKET

piezometer depth (m)	10.0	piezometer level (m)	8.677 m
backfilling materials	from depth (m)	to depth (m)	volume (m ³)
sand pocket	10.50	9.50	0.002
bentonite plug	9.50	8.50	0.002
bentonite grout	8.50	0.0	0.170
grout mix details	1:4	total standpipe length (m)	10.5 m

FALLING HEAD TEST

date of test	18/01/2002				
time of test	11:00 am.				
remarks	Basic Reading 2000 mm.				
					
time (min)	fall in head (mm)	time (min)	fall in head (mm)	time (min)	fall in head (mm)
0	0.0	4.0	1120 mm	12.0	3590 mm
0.5	150	4.5	1260	14.0	2930
1.0	260	5.0	1300	15.0	3250
1.5	595	6.0	1510	18.0	3530
2.0	670	7.0	1700	20.0	3780
2.5	750	8.0	1890	25.0	4390
3.0	870	9.0	2080	30.0	4900
3.5	985	10.0	2260		

date protective cover installed	25/02/02	final RL of standpipe top (m)	8.677
witnessed/approved by Engineer	PC GEO-MANAGEMENT SDN BHD (32549-A)		


BOREHOLE (all depths from ground level)

start date	15/01/2002	ground level (m)	18.746 m
depth (m)	description	casing dia (mm)	100
0	ground level		
8.50 m			
9.50 m			
10.50 m			
finish date	16/01/2002	driller's name	
final depth (m)	10.50		3 Foundation
total casing length (m)	10.70	total casing depth (m)	10.50

**STANDPIPE
PIEZOMETER**

PC GEO-MANAGEMENT SDN BHD (32549-A)
Kuala Lumpur, Malaysia
40400 8240869, 8240869
Tel: 03-5240864 Fax: 03-5240864
Durian Tunggal

piezometer ref no	date/time installed	11:30 am
SP-01	16/01/2002	
64-1	installed by	Hani3




soil centralab
sendirian berhad

SITE WORKSHEET

SHM

TYPICAL INSTALLATION DETAILS



marker reference no	location		date installed	top of marker level (m)	adjacent ground level (m)	remarks
	chainage (m)	offset (m)				
G1	CH 199.06		15.1.2002	13.891 m		
G2	CH 199.02		15.1.2002	16.080		
G3	CH 198.98		15.1.2002	19.098		
G4	CH 198.94		17.01.2002	19.017		
G5	CH 198.90		15.1.2002	17.854		
G6	CH 198.86		"	14.865		
G7	CH 198.82		"	11.053		
G8	CH 198.84		"	12.587		
G9	CH 198.88		"	13.706		
G10	CH 198.92		"	13.977		
G11	CH 198.96		"	14.066		
G12	CH 198.00		"	14.343		
G13	CH 199.06		"	8.513		
G14	CH 199.02		"	8.245 m		
G15	CH 198.98		"	7.973 m		
G16	CH 198.94		"	7.705		
G17	CH 198.90		15.1.2002	7.865		
markers installed by			HAKIM	level taken by	HAKIM	


GEO-MANAGEMENT SON BHD (3254)
6B Jalan Angsarik Vanilla M 31A
Kuala Lumpur, Selangor 50460
Tel: 03-5240869, 5240863, 5240864
Fax: 03-5240864

SETTLEMENT HEAVE MARKER

contract name	INS. WORKS AT KMM 199, DURIAN TUNGGAL
location	

sheet no

3




soil centralab
sendirian berhad

DATASHEET

SP2

DATE INSTALLED		16/01/2002		RL OF TOP OF STANDPIPE AS INSTALLED (m)		19.177	
LEVEL OF STANDPIPE AS INSTALLED (m)		8.677		RL OF GROUND ADJACENT TO STANDPIPE AT INSTALLATION (m)		18.746	
TOTAL LENGTH OF STANDPIPE INSTALLED (m)		10.50		TOTAL HEAD BASE READING (m)		10.017	
DATE	DAY NO	TIME	DIPMETER READING (m)	STANDPIPE TOP RL (m)	ADJACENT GROUND RL (m)	TOTAL WATER HEAD RL (m)	WATER HEAD RELATIVE TO BASE READING (m)
29/01/2002	1	15:15	9.160	19.177	18.746	10.017	0.000
19/02/2002	22	17:02	9.620	19.177	18.746	9.557	0.460
02/04/2002	64	12:35	9.800	19.177	18.746	9.377	0.640
23/04/2002	85	11:42	9.760	19.177	18.746	9.417	0.600
11/06/2002	134	13:38	9.650	19.177	18.746	9.527	0.490
09/07/2002	162	10:59	9.780	19.177	18.746	9.397	0.620
14/08/2002	198	11:10	7.830	19.177	18.746	11.347	-1.330
10/09/2002	225	11:16	7.900	19.177	18.746	11.277	-1.260
08/10/2002	253	10:51	7.700	19.177	18.746	11.477	-1.460
12/11/2002	288	10:35	7.520	19.177	18.746	11.657	-1.640
12/12/2002	318	12:47	7.690	19.177	18.746	11.487	-1.470
07/01/2003	344	14:00	7.980	19.177	18.746	11.197	-1.180
04/02/2003	372	12:45	8.720	19.177	18.746	10.457	-0.440
03/03/2003	399	11:14	8.310	19.177	18.746	10.867	-0.850
08/04/2003	435	11:22	9.060	19.177	18.746	10.117	-0.100
06/05/2003	463	12:05	7.980	19.177	18.746	11.197	-1.180
05/06/2003	493	13:50	8.650	19.177	18.746	10.327	-0.310
18/07/2003	536	11:04	9.618	19.177	18.746	9.559	0.458
19/07/2003	537	12:24	9.538	19.177	18.746	9.639	0.378
Rain:33.7mm							
20/07/2003	538	12:35	9.480	19.177	18.746	9.697	0.320
21/07/2003	539	12:55	9.330	19.177	18.746	9.847	0.170
22/07/2003	540	12:25	9.360	19.177	18.746	9.817	0.200
23/07/2003	541	12:12	9.300	19.177	18.746	9.877	0.140
04/08/2003	553	11:54	9.365	19.177	18.746	9.812	0.205
28/10/2003	638	13:34	8.480	19.177	18.746	10.697	-0.680
29/12/2003	700	13:06	8.470	19.177	18.746	10.707	-0.690
19/01/2004	721	12:09	9.150	19.177	18.746	10.027	-0.010



STANDPIPE PIEZOMETER

Project
Name

INSTRUMENTATION WORKS AT KM 199 (N/B), DURIAN TUNGGAL

Section


-

Chainage

198.94

Piezometer
Ref No

BH-1/SP-01



SSM

INSTRUMENTATION WORKS AT KM 199, DURIAN TUNGGAL

DATE STARTED 9.9.09		DEPTH (m)	DATE AND DEPTH OF BORING (m)	DEPTH TO WATER (m)	SAMPLES AND TESTS			OBSERVATIONS	STRATA			STRATA DESCRIPTION	'N' VALUE 10 20 30 40	LEGEND	
DATE COMPLETED 9.9.09					SAMPLES	DEPTH (m)	STANDARD		REDUCED LEVEL (m)	DEPTH (m)	THICK- NESS (m)				
BORING METHOD rotary wash boring		2	09.09.09	3.50	P-1 DS-1	0.00-1.50	2/2-2-2-2 N=8 R=0.28/0.45m	1.50	1.50	1.50	Wash Bore				
BOREHOLE DIAMETER 110mm					P-2 DS-2	1.50-1.95	2/1-2-2-2 N=7 R=0.35/0.45m				1.50			1.50	Firm, yellowish red SILT
CASING DEPTH / DIAMETER 100mm					P-3 DS-3 VS-1	3.00-3.45	2/1-1-1-1 N=4 R=0.30/0.45m Peak = 18.0kPa Rem = 5.5kPa R=0.95/1.00m				3.00			1.50	Firm, yellowish red, light yellow SILT
LOG BY Mohd Nizam Anuar					P-4 DS-4	4.50-4.95 5.00	2/1-1-1-1 N=4 R=0.30/0.45m Peak = 18.0kPa Rem = 5.5kPa R=0.95/1.00m				4.50			1.00	Soft, yellowish red, yellowish brown, light grey SILT
REMARKS					UD-1	5.50-6.50	3/4-4-8-7 N=23 R=0.40/0.45m				5.50			1.00	Top : Soft, yellowish yellow SILT Bottom : Soft, yellowish red, light grey SILT
SAMPLE / TEST LEGEND					P-5 DS-5	6.50-6.95	4/3-4-5-5 N=17 R=0.25/0.45m				6.50			1.00	Very stiff, light grey, yellowish red, light yellow SILT
UP thin walled piston					P-6 DS-6	8.00-8.45	7/5-6-6-5 N=22 R=0.27/0.45m				8.00			1.50	Very stiff, light grey, yellowish red, light yellow SILT
UT thin walled					P-7 DS-7	9.50-9.95	30/20-11-19/0.075m N=50/0.225m R=0.12/0.375m				9.50			1.50	Very stiff, light grey, light yellow SILT
UD open drive					P-8 DS-8	11.00-11.38	17/10-11-21-8/0.025m N=50/0.25m R=0.10/0.40m				11.00			1.50	Hard, light yellow SILT
DS SPT split spoon					P-9 DS-9	12.50-12.90	24/22-28/0.075m N=50/0.15m R=0.11/0.30m				12.50			1.50	Hard, yellowish light grey SILT
MZ mazier sample					P-10 DS-10	14.00-14.30	20-30/0.075m N=50/0.075m R=0.08/0.15m				14.00			1.50	Hard, yellowish light grey SILT
C rock coring		P-11 DS-11	15.50-15.65	23-27/0.075m N=50/0.075m R=0.09/0.15m	15.50	1.65	Hard, dark grey gravelly SILT								
BS bulk disturbed			17.00-17.15		17.15		END OF BOREHOLE DEPTH: 17.15m								
QS small disturbed															
WS ground water															
V vane shear test															
P pressuremeter															

soil centralab
sendirian berhad

CONTRACT NAME
SI WORKS FOR LPT PHASE 2 PKJ
5A

**BOREHOLE
RECORD**

BOREHOLE NO. **BH-8**
CHAINAGE / OFFSET (m) **54242**

GROUND LEVEL (m)


COORDINATES

FORM **B1**
PAGE **1**

PEMBANGUNAN SISTEM PEMANTAUAN CERUN DI KM 8.25,
JALAN JELAWANG-GUA MUSANG.

IPI 2 & VWP 4

DISPLACEMENT, WATER LEVEL VS DATE(S)





RST Instruments Ltd.

CUMULATIVE DISPLACEMENT

Inclinanalysis

Borehole : INC 3 - BH 5 (A)
Project : JELAWANG - GUA MUSANG
Location :
Northing :
Easting :

Spiral Correction : N/A
Collar Elevation :
Borehole Total Depth : 23.5 meters
North Groove Azimuth :
Base Reading : 2008 Aug 23 13:38



JALAN JELAWANG-GUA MUSANG.

SOIL MOISTURE 1, 2 & RAIN GAUGE (WATER INTENSITY) VS DATE(S)




7 May 2009-23 July 2009


— SM1 — SM2 — Water Intensity

23-07-2009

**INSTRUMENTATION WORKS AT KM 199 (NB),
DURIAN TUNGGAL
(SURFACE SETTLEMENT MARKER)
SETTLEMENT VS TIME**



SETTLEMENT VS TIME



ANALYSIS

- Asaoka Plot (1978)
- Matsuo Plot (1977)
- Varnes (1978)

Independent monitoring

MACKINTOSH PROBE



HUMAN ERRORS

- Drop height less than 280mm resulting in higher blow counts;
- Applying force to hammer (exerting) resulting in less blow counts;
- Penetration depth not marked correctly;
- Wrong counting.

MACKINTOSH PROBE



INSTRUMENTAL ERRORS

- Driving rod bent giving more blow counts;
- Stopper blow lost or damaged; torn or worn out threads on coupling;

For stiffer soils (normally residual soil), a different method of consistency definition is used taken from American practice which is based on SPT “N” value. The defined range of Cu is also given:

Consistency	SPT “N” Values	Cu Range (kPa)
Very soft	0 - 2	0 -12.5
Soft	2 - 4	12.5 - 25
Medium stiff	4 - 8	25 - 50
Stiff	8 -15	50 -100
Very stiff	15 - 30	100 - 200
Hard	30 and greater	200 and greater




For granular (coarse) soils the following method of relative density is used:

Relative Density	SPT “N” Values
Very loose	0 – 4
Loose	4 – 10
Medium dense	10 – 30
Dense	30 – 50
Very dense	50 and greater




Data collection, processing and presentation

Standpipe Piezometer



Data collection, processing and presentation

Inclinometer



Thank You