Minor Shallow Failure(<5m length)

Localised surficial loosening, localised evidence of fallen material (rock) at base slope

General evidence of fallen block and/or boulders (rock) at base slope

Failure affecting more than one berm but not whole slope

Failure extending height of slope

Cracks on embankment crest, road uneffected, no subsidence, no other evidence of failure



Arcuate cracks on road and/or depression less than 10cm- Otherwise no mass movement evident.


Slope failure with arcuate cracks on road and/or depression less than

2007/01/15


Slope failure with extensive arcuate cracks on road and/or depression greater than 10cm




Toppling/Wedge/Planar/Rockfall



Rotational/Translational/Slump





Translational


Original position Slumped mass Slump

Circular/Mud Flow/Debris Flow




Circular

Debris Flow





Creep/Subsidence



Layered bedrock bending down slope

Subsidence



Passable(only minor clearing work

requiered)



Passable but required immediate remedial work







Passable only after clearing/remedial work



<u>Closed until completion of major</u> <u>clearing remedial work</u>






Road, built up area (e:g. indoor car-park, building, mosque,church, temple, manned subtation, sewerage, treatment plant, railway, flyover,subway, reservoir, construction site,)

Densely used open space and public waiting area(e:g playground,

open car park, picnic area)



Lightly used open – air recreation area, non-dangerous good storage area, intensive agricultural area, golf course



No facilities present or remote area(e:g jungle, plantation, forest, low

intensity agricultural)

