

	MATERIAL/TYPE	CONDITION ANALYSIS	RATING (1 - 5)
	R.C. PIPE		3
	NONE		N/A
	NONE		N/A
	NONE		N/A
	R.C. PIPE		3
	BITUMINOUS		3
	NONE		N/A
	CONC. HEADWALL		-
	NONE		N/A
1.	NONE		N/A

CROSS SECTION

LONG SECTION