

FIRGURE 5: POSITION OF STRAIN GAUGES, LVDT AND PRECISE LEVEL IN BEAM AT MID SPAN





FIGURE 6: POSITION OF STRAIN GAUGES AND PRECISE LEVEL AT PIER 2



FIRGURE 7: POSITION OF ROSETTE AND PRECISE LEVEL AT ABUTMENT B

